## LICENSEE EVENT REPORT

CONTROL BLOCK:
7 8 9 LICENSEE GODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
O 1 SOURCE L 6 0 5 0 - 0 3 2 5 7 1 1 0 1 7 8 8 1 1 1 3 0 7 8 9
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  O 2 Containment oxygen monitor CAC - AT - 1263 was found inoperable by a control
O 3 operator during a routire panel check.
0 4 (Technical Specification B.3, 5.3)
0 5
0 6
0 7
7 9
SYSTEM CODE COLE SUBCODE COMPONENT CODE SUSCODE SUBCODE SUBCOD
LER/RO EVENT YEAR SEQUENTIAL ARPORT NO.  17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32  ACTION FUTURE EFFECT SHUTDOWN METHOD HOURS 22 SUBMITTED FORM SUB. SUPPLIER MANUFACTURER  A 18 7 19 Z 20 Z 21 0 0 0 0 0 N 23 N 24 N 25 B 1 3 5 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
defective and caused the monitor to fail. These components were replaced and the
monitor declared operable. This is considered an isolated event and no further
[1]   corrective action is required.
FACILITY STATUS OTHER STATUS OF DISCOVERY DESCRIPTION
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)  NA LOCATION OF RELEASE (36)  PERSONNEL EXPOSURES  NA 45
1 7 0 0 0 37 Z 38 NA NA
PERSONNEL INJURIES 13  NUMBER DESCRIPTION (41)  1 8 0 0 0 (40) NA
7 8 9 11 12 LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION (43)
1 9 Z 42 NA
7812070168 NAC USE ONLY NA NA
NAME OF PREPARER A. C. Tollison PHONE: 919-457-6701