

2

RECEIVED  
MDC  
1982 DEC 20 PM 1:38  
SCE  
REGION V TELEPHONE  
213-572-2796

**Southern California Edison Company**

P. O. BOX 800  
2244 WALNUT GROVE AVENUE  
ROSEMEAD, CALIFORNIA 91770

December 16, 1982

DAVID J. FOGARTY  
EXECUTIVE VICE PRESIDENT

U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region V  
1450 Maria Lane, Suite 210  
Walnut Creek, California 94596-5368

Attention: Mr. R. H. Engelken, Regional Administrator

Dear Sir:

Subject: Docket No. 50-206 and 50-361  
IE Inspection Report No. 50-206/82-33 and 50-361/82-33  
Response to Notice of Violation  
San Onofre Nuclear Generating Station  
Units 1 and 2

Mr. H. E. Book's letter of November 19, 1982, issued IE Inspection Report 50-206/82-33 and 50-361/82-33, and forwarded a Notice of Violation resulting from the October 25-28, 1982 routine radiation protection inspection conducted by Mr. G. P. Yuhas.

The enclosure to this letter provides our response to the Notice of Violation contained in Appendix A of Mr. Book's letter of November 19, 1982.

I trust the enclosure responds adequately to all aspects of the violation. If you have any questions or if we can provide additional information, please so advise.

Sincerely,



Enclosure

cc: L. F. Miller (USNRC Resident Inspector, San Onofre Unit 1)  
A. E. Chaffee (USNRC Resident Inspector, San Onofre Units 2&3)  
R. J. Pate (USNRC Resident Inspector, San Onofre Units 2&3)

ENCLOSURE

Response to the Notice of Violation contained in Appendix A of Mr. Book's letter of November 19, 1982.

ITEM

Appendix A of Mr. Book's letter of November 19 states:

"10 CFR 19.11(b) states that if posting of a document specified in 10 CFR 19.11(a) is not practicable, the licensee may post a notice which describes the document and states where it may be examined. Documents specified in 10 CFR 19.11(a) include: 10 CFR 19, 10 CFR 20; the license and license conditions.

"Contrary to this requirement, on October 27, 1982, the notice dated January 5, 1978 posted at several locations at Units 1 and 2 did not address the Unit 2 license, license conditions, or describe 10 CFR 19 and 20.

"This is a severity Level V violation (Supplement IV)."

RESPONSE

1. Corrective Steps Which Have Been Taken and Results Achieved

A new notice has been posted addressing the Unit 2 license, license conditions, 10 CFR 19 and 10 CFR 20.

2. Corrective Steps Which Will Be Taken To Prevent Further Items of Non-Compliance

An administrative procedure was issued which defines the material to be posted and assigns responsibilities for posting notices, instructions and reports for workers, as required by 10 CFR 19.11.

3. Date When Full Compliance Was Achieved

Full compliance was achieved on November 2, 1982 when the revised notice to all personnel, outlining the available documents, was posted.

NOV Units 1&2

PBK:6521