

Public Service Company of Colorado

P. O. Box 361, Platteville, Colorado 80651

December 6, 1978
Fort St. Vrain
Unit No. 1
P-78193

Mr. Karl V. Seyfrit, Director
Nuclear Regulatory Commission
Region IV
Office of Inspection and Enforcement
611 Ryan Plaza Drive
Suite 1000
Arlington, Texas 76012

REF: Facility Operating License
No. DPR-34

Docket No. 50-267

Dear Mr. Seyfrit:

Enclosed please find a copy of Reportable Occurrence Report No. 50-267/78-18/03-X-3, Final Supplement, submitted per the requirements of Technical Specification AC 7.5.2(b)2.

Also, please find enclosed one copy of the Licensee Event Report for Reportable Occurrence Report No. 50-267/78-18/03-X-3, Final Supplement.

Very truly yours,

Don Warembourg
Don Warembourg
Manager, Nuclear Production

DW/alk

cc: Director, Office of Management Information
and Program Control

7812130190

Dooz
5/11

5