

REVISION LOG SHEET

Revision Date: PORC 12-06-82 (issued 01-05-83)

This log sheet must be retained as the last page of the Browns Ferry Implementing Procedures Document.

Inserted by: _____

Date Inserted: _____

Pages to be Removed			New Pages to be Inserted		
Part	Page Number	Revision/ Date	Part	Page Number	Revision/ Date
List of Effective Pages	1 of 10	11/01/82	List of Effective Pages	1 of 10	12/06/82
IP-1	10 of 11	10/19/82	IP-1	10 of 11	12/06/82


TENNESSEE VALLEY AUTHORITY

BROWNS FERRY NUCLEAR PLANT IMPLEMENTING PROCEDURES DOCUMENT

LIST OF EFFECTIVE PAGES

This List of Effective Pages must be retained with the Browns Ferry Nuclear Plant Implementing Procedures Documents.

Part	Procedure Number	Subdivision	Page Number	Date/Rev. No.
BFN		List of Effective Pages	1 of 10	12/06/82
			2 of 10	11/30/82
			3 of 10	11/01/82
			4 of 10	11/01/82
			5 of 10	11/01/82
			6 of 10	11/01/82
			7 of 10	11/01/82
			8 of 10	11/01/82
			9 of 10	11/30/82
			10 of 10	11/01/82
		Table of Contents	1 of 1	10/19/82
	IP-1		Coversheet	10/19/82
		Preface	1 of 1	10/19/82
	IP-1		1 of 11	10/19/82
			2 of 11	10/19/82
			3 of 11	10/19/82
			4 of 11	10/19/82
			5 of 11	10/19/82
			6 of 11	10/19/82
			7 of 11	10/19/82
			8 of 11	10/19/82
			9 of 11	10/19/82
			10 of 11	12/06/82
			11 of 11	10/19/82
	IP-2		Coversheet	06/15/82
			1 of 2	04/22/82
			2 of 2	10/19/82



- * (1) Before initiating IP-2, confirm by noticeable building movement and/or call National Earthquake Information Center at (303) 234-3994. See FSAR Figure 2.5-7, Modified Mercalli Intensity IV.
- * (2) Before initiating IP-3, confirm by building movement, some damage to non-seismic structures. Call National Earthquake Information Center at (303) 234-3994. See FSAR Figure 2.5-7, Modified Mercalli Intensity VII.