

# Sinnissippi Alliance for the Environment

326 North Avon Street  
Rockford, Illinois 61103

June 28, 1982

Mr. J. M. Felton  
Division of Rules and Records  
Office of Administration  
Nuclear Regulatory Commission  
Washington, D.C. 20555

**FREEDOM OF INFORMATION  
ACT. REQUEST**

*FOIA-82-295  
Rec'd 7-7-82*

Dear Mr. Felton:

On behalf of the Sinnissippi Alliance for the Environment, I hereby request the below enumerated documents pursuant to the provision of the Freedom of Information Act, 5 U.S.C. Section 552:

1. All information pertaining to Westinghouse D4/D5 steam generators installed in the nuclear generating plant at Krysko, Yugoslavia, with particular reference to tube ruptures, denting, thinning, leaking, flow-induced vibration, turbulent buffeting and any other failures;
2. All literature which relate to the maintenance and/or refueling outages of the Krysko Plant as pertains to eddy current tests and inspection of the above mentioned steam generators; and
3. Items one through twenty-one on the attached Appendix referenced in file number FOIA-82-167.

I believe the above request qualifies for a waiver of fees since the information is requested for use in a licensing hearing, and its use is therefore in the public interest. If, however, you do not grant a fee waiver, then please consult me if duplicating costs exceed \$25.00. You may reach me at (815) 987-5760 during regular office hours. Also, if at all possible, I would appreciate your expediting my request, since time is of the essence.

Sincerely;



Richard Bunch

cc. Rep. Lynn Martin

8207050073

AppendixCategory four

1. 11/78 EG&G Idaho, Inc. report entitled, "Code Assessment and Applications Program, Steam Generator Tube Rupture Effects on a LOCA".

Category five

1. 5/81 Sweden - Ringhals 3 "Steam Generator Inspection Evaluation of Eddy Current Results".
2. 10/27/81 Telex No. 238 to Lafleur from Nordstrom, SKI - Sweden, "Primary to Secondary Leak in Ringhals 3".
3. 11/13/81 Memo to Denton from Lafleur, "Tube Failure of Preheater-Type Steam Generator", w/stated enclosures.
  - (a) Telex No. 269.
  - (b) Telex No. 238.
4. 11/18/81 Telex to Lafleur from Mandeus, SKI - Sweden, "Damages in Steam Generators in Ringhals 3".
5. 11/19/81 Sweden - Studsvik Arbetsrapport Technical Report No. ET-81/141, "Ringhals 3 Fretting Defects on Steam Generator Tubes".
6. 12/7/81 Sweden report, "Ringhals Unit 3 Tube Plugging".
7. 12/17/81 Letter to Lafleur from Weehuizen, ASK - Switzerland, "NRC Survey of Steam Generator Experience".
8. 12/18/81 Telex No. 315 to Lafleur from Mandeus, SKI - Sweden, "Ringhals 3 - Plugging of Steam Generator Tubes".
9. 1/82 Chart entitled, "Foreign Operating Experience with PWR Steam Generators", Belgium.
10. 1/12/82 Telex No. 27 to Lafleur from Van Daatselaar, NMSAE - Netherlands, "Your Letter of December 15, 1981 Regarding NRC Survey of Steam Generator Experience".

AppendixCategory five

11. 1/15/82 Telex No. 47 to Lafleur from Trueba, CSN - Spain, regarding NRC survey.
12. 1/20/82 Letter to Lafleur from Reisch, SKI - Sweden, w/attachments, regarding Ringhals 2 (steam generator problems) and 3 (steam generator tube fretting).
13. 2/9/82 Telex 230 to Lafleur from Mavko - IJS - Yugoslavia.
14. 2/16/82 Telex 566 to Lafleur from Zaffiro, CNEN - Italy.
15. 1-2/82 Chart, Table 4, "Foreign Operating Experience with PWR Steam Generators".
16. 1-2/82 Chart, "Foreign Operating Experience with P.W.R. Steam Generators (France)".
17. 1-2/82 Chart, "Foreign Operating Experience with P.W.R. Steam Generators".
18. 3/9/82 Telex to Lafleur from Mandeus, SKI - Sweden, "Application for Starting Ringhals 3".
19. 3/23/82 Telex No. 87 to Lafleur from Mandeus, SKI - Sweden, regarding Ringhals 3.
20. 4/6/82 Telex 100 to Lafleur from Hallencreutz, SKI - Sweden, regarding Ringhals 3.
21. Undated Viewgraphs entitled "Nuclear Power in Sweden".