NRC FORM 591 PART 1 U.S. NUCLEAR REGULATORY COMMISSION (7-91) SAFETY INSPECTION 10 CFR 2.201 Page 1 of 1. LICENSEE 2. REGIONAL OFFICE REGION II U.S. NUCLEAR REGULATORY COMMISSION 101 MARIETTA STREET NW SUITE 2900 ATLANTA GA 30323 5. DATE OF INSPECTION 3. DOCKET NUMBER(S) 4. LICENSE NUMBER(S) 1/26/94 LICENSEE: The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, inter-lews with personnel, and observations by the inspector. The findings as a result of this inspection are as follows: Within the scope of this inspection, no violations were observed. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time. During this inspection certain of your activities, as described below or attached, were in violation of raRC requirements. This form is a NUTICE OF VIOLATION, which is required to be posted in accordance with 10 CFR 19.11. was not properly posted to 10 CFR 20.203(b),(c),(d),(e) or 34.42. indicate the presence of a of sealed sources were not performed at the proper frequencies. 10 CFR _______ or License Condition Number C. Records of _____ were not properly maintained. or License Condition Number ___ Documents were not properly posted or otherwise made available. 10 CFR J.11. E. Reports or notification of were not made in accordance with or License Condition Number ommission has an II that activities aythorized by the treins would be instructed (4/220, A.) I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC. SIGNATURE - LICENS 250085 DATE SIGNATURE -- NRC INSPECTOR DATE

NRC FORM 591 Part 1 (1-91)

01\ IE07

NHC FORM 591 PART 2 (7-93) U.S. NUCLEAR REGULATORY COMMISSION 34 CFR 2.201 SAFETY INSPECTION Page 2 of 2 1. LICENSEE 2. REGIONAL OFFICE Bass Energy. Inc. REGION II U.S. NUCLEAR REGULATORY COMMISSION P.O. Box 206 101 MARIETTA STREET NW SUITE 2900 Bruceton Hills, West Virginia 26525 ATLANTA GA 30323 3. DOCKET NUMBER(S) 4. LICENSE NUMBER(S) 5. DATE OF INSPECTION 1/26/94 (Continued) The violations listed below are not being cited because they were self-identified, and corrective action was or is being taken, and the remaining criteria in 10 CFR 2, App. C, to exercise discretion were satisfied. facts 19,20,21, Eisens or lises application you not posted or the location There the documents could be viewed vos not come ded not plane could of energy of present national england on 1/7/93 OF

NRC FORM 591 PART 2 (2-91)