U.S. NUCLEAR REGULATORY COMMISSION

U.S. HOULEFULLEGOESTON COMMISSION

10 CFH 8. FO1		SAFETY	INSPECTION		Page 1 of /
PO Bo	DuPont de Bemours ox 1217 etsburg, WV 26102	& Co., Inc.	101 N	ON II IUCLEAR REGULATORY COMMIS MARIETTA STREET NW SUITE 290 NTA GA 30323	
3. DOCKET NU	MBER(S)	4. LICENSE NUMBER(5)	5 DATE OF INSPECTION	
030-06660		47-01876-01		2/15/94	
Regulatory Cor	nmission (MRC) rules and regi	ulations and the condition	ns of your license. The in	e to radiation safety and to comp aspection consisted of selective e sector. The findings as a result o	xaminations of
71	n the scope of this inspection,	no violations were observ	ved.		
	nspector also verified the step tions on those actions at this ti		ct the violations identifie	d during the last inspection. We	have no further
annual spress	mans on mose sounds at this ti	1110			
	g this inspection certain of you CE OF VIOLATION, which is re			in violation of NRC requirements 9.11.	s. This form is a
A				was not properly	posted to
	indicate the presence of a				b),(c),(d),(e) or 34.42.
Пв					
L				of sealed sources	were not
	performed at the proper freq	uencier =R	or Licent	se Condition Number	
C.	Records of			were not prope	rly maintained.
processing.	10 CFR	or License Condition 1	Number		
D.	Documents were not properly	y posted or otherwise ma	de available. 10 CFR 19	.11.	
E	Reports or notification of		were not made in	n accordance with	
house		or License Condition I	Vumber		
ГП.	TO OTTO and the second distribution of the second s	or cidense condition (VU/TIDE!		
I hereby state the above. This state unless required	stement of corrective actions is	s described by me to the made in accordance wit	Inspector will be taken to the requirements of 10	o correct the violations identified 0 CFR 2.201. No further response	in the Items checked will be submitted
SIGNATURE - I	LICENSEE	DATE	SIGNATURE NRC IN	ISPECTOR	DATE/
	03250176 940215		1 1		2/1/2/
(1)	MDUCK 030086	60	and the same and the		11137 74