

APPENDIX A
NOTICE OF VIOLATION

Georgia Power Company
Hatch 1 & 2

Docket Nos. 50-321, 50-366
License Nos. DPR-57, NPF-5

As a result of the inspection conducted on November 30 - December 6, 1982 and in accordance with the Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified.

Environmental Technical Specification 5.3.2.2 requires that audits of facility activities shall be performed, at least, once a year under the cognizance of the SRB to ensure conformance of facility operation to all provisions of the Environmental Technical Specifications (ETS). ETS-3.2, Table 3.2-1, specifies the performance of an analytical program.

Contrary to the above, audits of the analytical program were not performed in 1980, 1981, and 1982, through December 6, 1982.

This is a Severity Level IV Violation (Supplement II).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Date: _____