APPENDIX A

NOTICE OF VIOLATION

Maine Yankee Atomic Power Company Maine Yankee Atomic Power Station Docket No. 50-309 License No. DPR-36

As a result of the inspection conducted on November 29, 1982 - January 4, 1983, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C) published in the Federal Register on March 9, 1982 (47 FR 9987), the following violation was identified:

Technical Specification 5.12 requires any individual permitted to enter a high radiation area, to be provided with a continuous? reading radiation dose rate monitoring device or a continuously integrating radiation dose rate device which alarms at a preset setpoint; or to be accompanied by a health physics qualified individual with a radiation dose rate monitoring device.

Contrary to the above, on December 6, 1982 two individuals, authorized by Raddation Work Permit (RWP) #82-12-166, entered high radiation areas (greater than 100 mrem/hr) within the containment building without either carrying a radiation survey meter or being accompanied by a health physics qualified individual with a radiation dose rate monitoring device.

This is a Severity Level IV violation (Supplement IV.D.).

Pursuant to the provisions of 10 CFR 2.201, Maine Yankee Atomic Power Company is hereby required to submit to this office within thirty days of the date of the letter transmitting this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) the corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending the response time.

B302150487 830131 PDR ADOCK 05000309 PDR	NRC FORM 318 (10-80) NRCM: '240	OFFICIAL	RECORD C	OPY	USGPO: 1981-335-960
8302150487 830131 PDR ADOCK 05000309		***************************************			
8302150487 830134	G ADOCK 05000309				
	8302150487 83012				