TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

February 4, 1983

Mr. James P. O'Reilly, Director U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 2 - DOCKET NO. 50-328 - FACILITY OPERATING LICENSE DPR-79 - REPORT 3 E OCCURRENCE REPORT SQR0-50-328/83004

The enclosed report provides details concerning the discovery of low baron concentration in the refueling water storage tank during routine testing. This report is submitted in accordance with Sequoyah unit 2 Technical Specification 6.9.1.13.b.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

Director of Nuclear Power

Enclosure cc (Enclosure): Document Control Desk U.S. Nuclear Regulatory Commission Washington, D.C. 20555

> Records Center Institute of Nuclear Power Operations Suite 1500 1100 Circle 75 Parkway Atlanta, Georgia 30339

NRC Inspector, Sequoyah

8302150544 830204 PDR ADOCK 05000328 S PDR

OFFICIAL COPY TE 22

5.4