

yellow

DEC 21 1982

Virginia Electric and Power Company
ATTN: Mr. W. L. Stewart, Vice President
Nuclear Operations
P. O. Box 26666
Richmond, VA 23261

Gentlemen:

Subject: Report No. 50-280/82-33 and 50-281/82-33

This refers to the routine safety inspection conducted by Mr. C. M. Hosey of this office on November 1-5, 1982, of activities authorized by NRC Operating License Nos. DPR-32 and DPR-37 for the Surry facility. Our preliminary findings were discussed with Mr. J. L. Wilson at the conclusion of the inspection.

Areas examined during the inspection and our findings are discussed in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

During the inspection, it was found that certain activities under your license appear to violate NRC requirements. These and references to pertinent requirements are listed in the Notice of Violation enclosed herewith as Appendix A. Elements to be included in your response are delineated in Appendix A.

In accordance with 10 CFR 2.790(a), a copy of this letter and the enclosures will be placed in the NRC's Public Document Room unless you notify this office, by telephone, within ten days of the date of this letter and submit written application to withhold information contained therein within thirty days of the date of this letter. Such application must be consistent with the requirements of 2.790(b)(1).

The responses directed by this letter and the enclosures are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

H. C. Dance, Chief
Project Branch 2
Division of Project and
Resident Programs

Enclosures (See Page 2)

8302150589 830207
PDR ADOCK 05000280
PDR
Q

DEC 21 1982

Enclosures:

- 1. Appendix A, Notice of Violation
- 2. Inspection Report Nos. 50-280/82-33
and 50-281/82-33

cc w/encls:

- J. A. Ferguson, Executive
Vice President-Power
- J. L. Wilson, Station Manager
- P. G. Godwin, Director, Nuclear Security

bcc w/encls:

Document Management Branch
Commonwealth of Virginia

RII *cmh*
CMHosey:es
12/10/82

RII *KPB*
KPBarr
12/13/82

RII *AG*
AFGibson
12/13/82

RII *Jfa*
KDLandis
12/17/82

RII *Jfa*
HCDand
12/17/82