

General Offices: 1945 West Parnall Road, Jackson, MI 49201 • (517) 788-0550

August 27, 1982

James G Keppler, Administrator Region III US Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

DOCKET 50-255 - LICENSE DPR-20 -PALISADES PLANT - LICENSEE EVENT REPORT 82-22 (IMPROPER VALVE)

On the reverse side is Licensee Event Report (LER) 82-22 (Incorrect Valve) which is reportable per Technical Specification 6.9.2.b(3).

Buan D. Johnson

Brian D Johnson Staff Licensing Engineer

CC Director, Office of Nuclear Reactor Regulation Director, Office of Inspection and Enforcement NRC Resident Inspector - Palisades

TE22