DE

MAR 2 3 1994

Docket No. 50-219

Mr. John J. Barton Vice President and Director GPU Nuclear Corporation Oyster Creek Nuclear Generating Station P.O. Box 388 Forked River, New Jersey 08731

Dear Mr. Barton:

SUBJECT: INSPECTION REPORT NO. 50-219/93-28

This refers to your February 22, 1994, correspondence, in response to our letter dated January 14, 1994, regarding Oyster Creek. This correspondence dealt with an inadequate procedure for electrically backseating valves and problems with your procedure review process. We have reviewed this matter in accordance with NRC Inspection Manual Procedure 92702.

Thank you for informing us of the corrective and preventive actions documented in your letter. We consider these actions acceptable pending further review in a future inspection of your licensed program.

We appreciate your cooperation.

Sincerely,

Richard J. Conte, Chief BWR Section, Operations Branch Division of Reactor Safety

OFFICIAL RECORD COPY G:OC9328R

9403290033 940323 PDR ADOCK 05000219 G PDR

IEO/

CC!

M. Laggart, Manager, Corporate Licensing G. Busch, Manager, Site Licensing, Oyster Creek Public Document Room (PDR) Local Public Document Room (LPDR) Nuclear Safety Information Center (NSIC) K. Abraham, PAO (2) (w/copy of letter dtd February 22, 1994) NRC Resident Inspector State of New Jersey (w/copy of letter dtd February 22, 1994)

bee:

Region I Docket Room (with concurrences) J. Rogge, DRP A. Burritt, DRS DRS File

bee (VIA E-MAIL): V. McCree, OEDO J. Stelz, NRR/PD 1-4 A. Dromerick, NRR/PD 1-4 M. Shannon, NRR/ILPB

(VIA E-MAIL AND NO ATTACHMENTS): R. Conte, DRS

RI:DRS Burritt/dmg AUT

03/15/94

REDRS

OFFICIAL RECORD COPY G:OC9328R