			Harrison	
NRC Form 591			U.S. NUCLEAR REGULATORY COMMISSIO	N
(12 B1) 10 CFR 2.201	SAFETY INSPECTION		EU 1/86	
1. LICENSEE		2. REGIONAL OFFIC	E	
CONSOLIDATED BIOMEDICAL LABS, INC. Richmond, Virginia		U. S. Nuclear Regulatory Commission 101 Marietta Street, Suite 2800 Atlanta, Georgia 30303		
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)		5. DATE OF INSPECTION	
030-17000	45-19166-01		1/21/83	
Licensee	42-15100-01			
those actions at this time.  3. During this inspection certain of your activitie  THIS IS A NOTICE OF VIOLATION which is	taken to correct the violat s, as checked below, were s required to be posted in	ions identified during th in violation of NRC req accordance with 10 CFF	e last inspection. We have no further questions on uirements.	nce
			of sealed sources were not performed at the prop	
frequencies 10 CFR		License C	condition Number	HEIT.
D. Records of		na Linnara Condition No.	were not properly maintaine	d.
10 CFA		or License Condition No	mber	
E. Documents were not properly posted or ot	herwise made available. 1	0 CFR 19.11.		
F. Reports or notifications of			were not made in accordan	Ce
with 10 CFR		or License Condition Nu	imber	
<b>Н</b> .				
J				
Пк				
I hereby state that within 30 days the actions described This statement of corrective actions is made in accordance NRC.	ed by me to the inspector dance with the requiremen	will be taken to correct ts of 10 CFR 2.201. No	the violations identified in the items checked above further response will be submitted unless required	e. by
8302150667 830121 NMS LIC30 45-19166-01 PDR		1/4 7	1 Depun 1/1/1/	
SIGNATURE - LICENSEE	DATE	SIGNATUI	RE - NRC INSPECTOR DATE	