	ENSEE		2. REGIONAL OFFICE		
INDUSTRIAL NOT SERVICES Division JIJH WENDELL AVENME INDIANAPOLIS, INDIANA 46202			U.S. Nuclear Regulatory Commission Office of Inspection & Enforcement Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137		
0	30-12208		147-04	8-25-82	
The in Comm		nditions of your license. Th	e inspection consisted of se	radiation safety and to compliance with the elective examinations of procedures and repre- t of this inspection are as follows:	
X	No items of noncompliance or uns	afe conditions were fou	nd.		
The	following items of noncompliance r	elated to records, signs, a	and labels were found:		
	A. Rooms or areas were not properly posted to indicate the presence of a RADIATION AREA. 10 CFR 20.203(b) or 34.4				
	B. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c) (1) or 34.42				
	C. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d)				
	D. Rooms or areas were not prope	D. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e)			
		E. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f) (1) or (f) (2)			
	F. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted or made available. 10 CFR 20.206(b)				
	G. FormNRC-3 was not properly posted. 10 CFR 20.206(c)				
	H. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 34.33(b)				
	I. Records of surveys or disposals were not properly maintained. 10 CFR 20.401(b) or 34.43(d)				
	J. Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.51, 40.61 or 70.51				
	K. Records of leak tests were not maintained as prescribed in your license, or 10 CFR 34.25(c)				
	L. Records of inventories were not maintained. 10 CFR 34.26				
	M. Utilization logs were not maintained. 10 CFR 34.27				
	N. Records of radiation survey instrument calibration were not maintained. 10 CFR 34.24				
	D. Records of teletherapy electrical interlock tests were not maintained as prescribed in your license.				
	P. Other				
		De	mall R. St (NRC Inspe	Worn	
	e NRC Inspector has explained a ncompliance will be corrected wi			and the second	
S N	B2090B0192 B20B25 NMS LIC30 13-06147-04 PDR	The list of unyo	IE	HQ FILE COPY	
1.1	D GOLTT OT FUR		. 1	DMB IE:07	