

DRS

MAR 22 1994

Docket No. 50-166

Dr. George E. Dieter, Dean
College of Engineering
University of Maryland
Engineering Classroom Building
Room 1137D
College Park, Maryland 20742

Dear Dr. Dieter:

Subject: NRC Inspection No. 50-166/94-01

Enclosed is a corrected transmittal letter for Inspection Report No. 50-166/94-01. The original transmittal letter was dated February 25, 1994 and contained an error in the date of the inspection. The inspection was conducted on January 25-31, 1994, rather than 1993, as indicated. We apologize for any inconvenience this may have caused you.

Sincerely,

Original Signed By:
Richard R. Keimig

JK
James H. Joyner, Chief
Facilities Radiological Safety
and Safeguards Branch
Division of Radiation Safety
and Safeguards

Enclosure: Corrected Transmittal Letter for Report No. 50-166/94-01

9403290132 940322
PDR ADDCK 05000166
G PDR

OFFICIAL RECORD COPY

IE 06

University of Maryland

2

cc w/encl:

Dr. W. Chappas, Reactor Director

Dr. G. Pertmer, Director, Nuclear Engineering Program

Dr. M. Wuttig, Chairman, Department of Materials and Nuclear Engineering

Dr. William Vernetson, TRTR

K. Abraham

Public Document Room

Local Public Document Room (LPDR)

Nuclear Safety Information Center (NSIC)

State of Maryland (2)

bcc w/encl:

Region I Docket Room (w/concurrences)

T. F. Dragoun, DRSS

S. Holmes, DRSS

S. Weiss, NRR (OWFN 10D21)

J. Caldwell, NRR/LOLB (OWFN 10D22)

V. McCree, OEDO

RE: DRSS

Joyner

03/2/94