Docket No. 50-373

Commonwealth Edison Company ATTN: Mr. Cordell Reed Vice President Post Office Box 767 Chicago, IL 60690

Gentlemen:

This refers to the special safeguards inspection report (50-373/82-30 (DETP) transmitted to you by letter dated August 24, 1982. The number assigned to this report is incorrect. The correct report number is 50-373/82-39(DETP). Please make pen-and-ink changes to page 2 of our transmittal letter and the Inspection Summary page. Thank you for your cooperation. We regret any inconvenience:

Sincerely,

James R. Miller, Chief Technical Inspection Branch

cc: Louis O. DelGeorge, Director of Nuclear Licensing D. L. Shamblin, Site Construction Superintendent T. E. Quaka, Quality Assurance Supervisor R. H. Holyoak, Station Superintendent B. B. Stephenson, Project Manager DMB/Document Control Desk (RIDS) Resident Inspector, RIII IE Files NMSS/SGPL NRR/DL/SSPB Karen Borgstadt, Office of

DMB: