

FEB 10 1983

30-08715

South Suburban Hospital
ATTN: Mr. Alan J. Sprintz
Executive Vice President
17800 South Kedzie Avenue
Hazel Crest, IL 60428

License No. 12-15191-01

Gentlemen:

This refers to the routine safety inspection conducted by Dr. L. W. Shatterly and Mr. D. R. Gibbons of this office on January 24, 1983, of activities authorized by NRC Byproduct Material License No. 12-15191-01 to the discussion of our findings with you, Mr. Robert Rutkowski and selected members of your staff at the conclusion of the inspection.


The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in noncompliance with NRC requirements, as specified in the enclosed Appendix. A written response is required.

The responses directed by this letter (and the accompanying Notice) are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



D. G. Wiedeman, Chief
Materials Radiation Protection
Section 1

Enclosure: Appendix,
Notice of Violation

cc w/encl:

Enrique Schwarz, M.D., RSO
John M. Nayden, M.D., Chief, Nuclear
Medicine Dept.

Mr. John S. Froemke, Manager,
Diagnostic Imaging
DMB/Document Control Desk (RIDS)

RIII

RIII

RIII

Shatterly/jp
2/8/83

Gibbons

Wiedeman
2/9/83

IE HQ FILE COPY

DMB:IE07

8302160191 830210
NMS LIC30
12-15191-01 PDR