

John D. O'Toole
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003
Telephone (212) 460-2533

August 25, 1982

Re: Indian Point Unit No. 2
Docket No. 50-247
LER-82-031/99X-0


Mr. Ronald C. Haynes,
Regional Administrator-Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406

Dear Mr. Haynes:

The attached Licensee Event Report LER-82-031/99X-0 is hereby submitted in accordance with the requirements of I.E. Bulletin No. 80-24, Item 2.f.

Three copies of this letter and the attachment are enclosed as required.

Very truly yours,



attach.

cc: Mr. Richard DeYoung, Director (30 copies)
Office of Inspection and Enforcement
c/o Distribution Services Branch, DDC, ADM
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. William G. McDonald, Director (3 copies)
Office of Management Information and Program
Control
c/o Distribution Services Branch, DDC, ADM
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. T. Rebelowski, Senior Resident Inspector
U. S. Nuclear Regulatory Commission
P. O. Box 38
Buchanan, New York 10511

8209130054 820825
PDR ADDCK 05000247
S PDR

IERU