

BALTIMORE GAS AND ELECTRIC COMPANY

DESIGNATED ORIGINAL

P.O. BOX 1475

BALTIMORE, MARYLAND 21203

mal

NUCLEAR POWER DEPARTMENT
CALVERT CLIFFS NUCLEAR POWER PLANT
LUSBY, MARYLAND 20657

August 25, 1982

Mr. Ronald C. Haynes, Director
U. S. Nuclear Regulatory Commission
Region 1
631 Park Avenue
King of Prussia, PA 19406

Docket No. 50-318
License No. DPR 69

SUBJECT: LER 82-39, Unit 2


Dear Mr. Haynes:

This letter is to confirm our verbal notification of your Mr. Dave Trimble of the discovery that both emergency airlock doors were simultaneously open for a brief period of time.

At 1030 on August 24, 1982 while Unit No. 2 was in Mode 3, an employee upon opening the outer emergency airlock door discovered that the inner door was also partially open, creating a violation of containment integrity (T.S. 3.6.1.3). The doors were shut at 1032, terminating the event. The release from this event totaled 825 microrcuries which resulted in a dose at the site boundary of 4.83×10^{-8} mR, which is far less than Technical Specification limits.

A complete description of the events leading to the discovery, and any further corrective action will be addressed in a follow-up report.

Very truly yours,


L. B. Russell
Plant Superintendent

LBR:bsg

cc: J. A. Tiernan
Director, Office of Management
Information & Program Control
ls

R. M. Douglass
R. E. Architzel
L. B. Russell

IE29