DCS No: 03020934940324 Date: March 25, 1994

PRELIMINARY NOTIFICATION OF EVENT OR UNUSUAL OCCURRENCE PN1-9421

This preliminary notification constitutes EARLY notice of events of POSSIBLE safety or public interest significance. The information is as initially received without verification or evaluation, and is basically all that is known by the Region I staff on this date.

Facility: Interstate Nuclear Service Corporation Royersford, Pennsylvania 19468	Liteusee Emergency Classification: Notification of Unusual Even Alert Site Area Emergency General Emergency
Docket No.: 030-20934	Not Applicable

Docket No.: 030-20934 License No.: 37-23341-01

Event No.: N/A

Event Location Code: MAT

Subject: HIGHWAY ACCIDENT

At 10:51 a.m. on March 24, 1994, a tractor-trailer truck, leased by Interstate Nuclear Service Corporation (INS), Royersford, Pennsylvania, (NRC License No. 30-23341-01) and containing 22 bins of decontaminated clothing, was involved in an accident with a private automobile while returning to the Susquehanna Nuclear Power Plant site. One person in the automobile was killed and another was air lifted to the hospital. The driver of the truck did not appear to have been physically injured but was also taken to the hospital under shock.

The truck left the INS laundry facility at about 9:30 a.m. today. INS reported that it was surveyed before leaving INS and the highest dose rate result was 0.2 mrem/hr on contact with the surface of the trailer (less than 0.05 mrem/hr at one meter from the surface). The highest reading at the surface of the bins of decontaminated clothing was also 0.2 mrem/hr and 0.1 mrem/hr at one meter from the surface of the bins. Personnel from a local Fire Department in the area of the accident conducted a radiation survey of the trailer. They measured a dose rate of 0.23 mrem/hr at the surface of the trailer.

The truck was not badly damaged by the accident and is believed to be in driveable condition. The doors of the trailer did not open as a result of the accident and no decontaminated clothing escaped the vehicle.

The accident occurred on Pennsylvania Route 61 at the intersection of Route 895, near Deer Lake, Pennsylvania. The Pennsylvania State Police, Schuylkill Haven Barracks, and the local fire department responded to the accident. Pennsylvania Department of Environmental Resources and Pennsylvania Emergency Management Agency followed up on the incident and provided guidance to the emergency responders.

The tractor-trailer will be towed to the company from which it was leased in Temple, Pennsylvania, where it will be checked for mechanical damage before it resume its trip to Susquehanna.

The Commonwealth of Pennsylvania has been informed.

This information is current as of 2:30 p.m. on 3/24/94.

300035

9403310007 940325 PDR I&E PNO-I-94-021 PDR 110

£-34

DCS No: 03020934940324

Date:

March 25, 1994

PRELIMINARY NOTIFICATION OF EVENT OR UNUSUAL OCCURRENCE PNI-9421

Region I i	s prepared	to respond to	media inquries.
------------	------------	---------------	-----------------

Contact:

C. T. Oberg 610-337-5202 M. M. Shanbaky

610-337-5202

DISTRIBUTION:

OWFN

MNBB AEOD

L-St. PDR NL RES

Mail:

ADM: DMB

DOT: Trans only **

Chairman Selin Comm. Rogers Comm. Remick

IRM

OIG

Comm. de Planque

OCAA OIP

NRC Ops Ctr

Phillips

OCA

EDO

ACRS

OGC OPA

NMSS

NRR** (Phone Verif: A. Byrdsong 964-1168 or 964-1166)

OE

OSP

Regional Offices

RI Resident Office

EWW

OIG

Licensee:

(Reactor Licensees)

Region I Form 83 (Rev. August 1993)

^{**} General list for sending PNs by FAX