

SEP 8 1982

UPA Technology, Inc.
ATTN: Mr. Sidney Lieber
President
7667 W. 95th Street Suite 3E
Hickory Hills, IL 60457

License No. 12-19833-01

Gentlemen:


This refers to the routine safety inspection conducted by Mr. J. R. Madera of this office on August 25, 1982, of activities authorized by NRC Byproduct Material License No. 12-19833-01 and to the discussion of our findings with Mrs. Jadwiga Strzelczk and Mr. Wayne B. Slugocki at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



D. G. Wiedeman, Chief
Materials Radiation Protection
Section 1

cc: Mrs. Jadwiga Strzelczk, RSO
DMB/Document Control Desk (RIDS)

RIII *[Signature]*
Madera/jp
9/2/82

RIII *[Signature]*
Wiedeman
9/2/82

IE HQ FILE COPY

8209130293 820908
NMS LIC30
12-19833-01 PDR

DMB:IE07