


WE Western Piping & Engineering Co., Inc.
Nuclear Components Division
1485 Yosemite Avenue, San Francisco, California 94124 (415) 822-6464

United States
Nuclear Regulatory Commission
Region IV
611 Ryan Plaza, Suite 1000
Arlington, Texas 76011

8/16/82



Reference: Docket # 99900302/82-01

Att: Mr. Uldis Potapovs Chief Vendor Programs Branch

In response to the above report, we offer the following Corrective Action and Recurrence Prevention.

CORRECTIVE ACTION

The three instruments noted as not being entered on the Inspection Usage Log were entered at the time of the finding, in addition to the above a review was performed of all instruments under the existing calibration system to assure that no other conditions exist.

Date of completion May 21, 1982.

RECURRENCE PREVENTION

A training secession was held with all inspection personnel to reemphasize the requirements of the Q.A. Manual and supporting procedures.

Date of completion May 22, 1982.

I hope the above response is adequate, if you have any questions please contact me.

Sincerely

Western Piping & Engineering Co.

A handwritten signature in cursive script that reads "R.M. Haytack".

R.M. Haytack Manager Quality Assurance

8209140159 820909
PDR QA999 EECWESTP
99900302 PDR

cc: K.A. Friedman Pres.
J.C. Flaherty V.P.
J.D. Kortuem Q.C. Mgr.
File