

71-0783




NORTHWEST INSPECTION & TESTING SERVICES, INC.

P.O. Box 50799
Idaho Falls, ID 83405
PHONE: (208) 529-9408

19007 61st Ave. N. E. Unit #5
Arlington, WA 98223
PHONE: (206) 435-9188

March 24, 1994



Director
Office of Nuclear Materials Safety & Safeguards
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Docket # 11-27394

Reply to Notice of Violation

Sir:

Enclosed please find the Quality Assurance (QA) Program for Northwest Inspection & Testing Services, Inc. (NITSI)

Corrective action is taken to avoid further violations by performing actions when advised of discrepancies.

NITSI anticipates that full compliance will be achieved by the submittal of this letter the enclosed QA Program.

NITSI's license number is 11-27394-01, NITSI utilizes a Technical Operations Model 660 and Industrial Nuclear Co. IR-100 for transport of radioactive material. When shipped commercially, an approved overpack is utilized. We would like to be registered as a user of the specific packagings in accordance with 10 CFR & 71.112 (c) (3).

If I may be of further service or information in this matter, please do not hesitate to contact me.

Sincerely,

William H. Shamel
Radiation Safety Officer

WHS/ngs
CC: Region IV

010010

94-0685

IE-07
11

9404010108 940324
PDR ADOCK 0710073B
C PDR