License No. SUA-1401

Uranerz, U.S.A., Inc. ATTN: Len Marrs, Manager of Operations 800 Werner Court, Suite #140 Casper, Wyoming 82601

Gentlemen:

This refers to the inspection conducted by Mr. C. E. Johnson of this office on August 2-3, 1982, of activities authorized by NRC Source Material License No. SUA-1401, and to the discussion of our findings with you and other members of your staff at the cuclusion of the inspection.

Areas examined during the inspection and our findings are documented in the enclosed inspection report.

Within the scope of the inspection, no violations or deviations were identified.

In accordance with 10 CFR 2.790(a), a copy of this letter and the enclosure will be placed in the NRC Public Document Room unless you notify this office, by telephone, within 10 days of the date of this letter and submit written application to withhold information contained therein within 30 days of the date of this letter. Such application must be consistent with the requirements of 2.790(b)(1).

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

Glen D. Brown, Chief Technical Programs Branch

Enclosure:

Appendix - NRC Inspection Report 40-8783/82-01

8209140183 820825 PDR ADOCK 04008783 C PDR IE 07

OFFICE	ES	ES	RPB2	TPB AV	DRRPREP	RA-RIV	
DATE	8/23/82		utt WCSeidle 8/23/82		JEGagliardo 8/25/82	RA-RIV JTMollins 8/ 6/82	
IRC FORM	1 318 (10/80) NRCM	0240	OFFICIAL	RECORD C	OPY		

NRC Inspection Report No. 40-8783/82-01

bcc to DMB for dist. <u>G-6</u> AEOD/NR IE/DFFMS/FFMB01 NMSS NRC PDR

bcc dist. by RIV
Regional Administrator
TP Branch
C. E. Johnson
MIS Section
RPB-2 Files

NRC FORM 318 | 10-80 | NRCM 0240

OFFICIAL RECORD COPY