APPENDIX A

NOTICE OF VIOLATION

Southern California Edison Company San Onofre Nuclear Generating Station Unit 2 Docket No. 5U-361

As a result of the inspection conducted during the period of December 22, 1982 to January 19, 1983 and in accordance with NRC Enforcement Policy, (10 CFR Part 2, Appendix C), 47 FR 9987 (March 9, 1982) the following violation was identified:

A. 10 CFR 20.203(f) states, in part:

- "(1) ...each container of licensed material shall bear a durable, clearly visible label identifying the radioactive contents.
- (2) A label required pursuant to paragraph (f)(1) of this section shall bear the radiation caution symbols and the words "CAUTION, RADIOACTIVE MATERIAL" or "DANGER, RADIOACTIVE MATERIAL."

Contrary to the above requirement, on December 22, 1982, an unlabeled 30 gallon drum was located outside of the biological sheild on the 15 foot elevation level of the containment building. This 30 gallon drum contained radioactively contaminated seals which had been removed from the reactor coolant pumps. The maximum radiation level at the surface of the drum was 0.005 rem/hour as measured by licensee personnel.

This is a severity level V violation (Supplement IV).

No written response is required.

JAN 28 1003

Original signed by D. F. Kusch

D. F. Kirsch, Chief Reactor Projects Section No. 3

Dated

8302230258 830128 PDR ADOCK 0500036