



South Carolina Electric & Gas Company
P.O. Box 88
Jenkinsville, SC 29065
(803) 345-4040

John L. Skolds
Vice President
Nuclear Operations

March 25, 1994
Refer to: RC-94-0089

Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, DC 20555

Attention: Mr. G. F. Wunder

Gentlemen:


Subject: VIRGIL C. SUMMER NUCLEAR STATION (VCSNS)
DOCKET NO. 50/395
OPERATING LICENSE NO NPF-12
TECHNICAL SPECIFICATION CHANGE - TSP 930002
LIMITING SAFETY SYSTEM SETTINGS - REACTOR TRIP SYSTEM
INSTRUMENTATION TRIP SETPOINTS
ENGINEERED SAFETY FEATURES ACTUATION SYSTEM
INSTRUMENTATION SETPOINT
SUPPLEMENT 1 - REVISED PAGE NUMBERS

Refer to: John L. Skolds to G. F. Wunder Letter dated
March 11, 1994, RC-94-0073

Due to the discovery of missing page numbers on several of the Technical Specification (TS) pages submitted in the referenced letter, South Carolina Electric & Gas Company (SCE&G) is submitting the attached revised pages for the purpose of having the "final" TS pages included on the docket. Although not all the pages in Enclosure 1 were affected, a complete Enclosure 1 is attached to minimize confusion.

I declare that the statements and matters set forth herein are true and correct to the best of my knowledge, information, and belief.

Should you have any questions concerning this issue, please call Mr. Philip Rose at (803) 345-4052 at your convenience.

Very truly yours,


John L. Skolds

PAR:dr
Enclosures

c: O. W. Dixon Jr.
R. R. Mahan (w/o Enclosures)
R. J. White
S. D. Ebnetter
NRC Resident Inspector

J. B. Knotts Jr.
A. A. Craft (DHEC)
Central File System
RTS (TSP 930002)
File (813.20)

010015

NUCLEAR EXCELLENCE - A SUMMER TRADITION!

9404040151 940325
PDR ADDCK 05000395
P PDR

ADD 1

PROPOSED TECHNICAL SPECIFICATION CHANGE REQUEST - TSP 930002
 VIRGIL C. SUMMER NUCLEAR STATION

LIST OF AFFECTED PAGES

<u>PAGE</u>	<u>SECTION</u>	<u>CHANGE DESCRIPTION</u>
2-4	2.2.1	Deleted Equation 2.2-1 due to 2 column format change.
2-5	Table 2.2-1	Deleted TA, Z, & S columns from Table due to 2 column format change.
2-6	Table 2.2-1	Deleted TA, Z, & S columns from Table due to 2 column format change. Revised Allowable Values to Function 13 "Steam Generator Water Level Low-Low" and Function 14 "Steam/Feedwater Flow Mismatch Coincident with Steam Generator Water Level Low-Low" due to PMA uncertainties.
2-7	Table 2.2-1	Deleted TA, Z, & S columns from Table due to 2 column format change.
2-9	Table 2.2-1, Note 3	Revised OVERPOWER DELTA T equation - administrative change due to typographical error.
2-10	Table 2.2-1, Note 3	Revised OVERPOWER DELTA T definition - administrative change due to typographical error.
B 2-3	B 2.2.1	Deleted discussion on methodology of determining operability when setpoint is found to exceed Allowable Value, due to 2 column format change.
3/4 3-15	3.3.2	Deleted Equation 2.2-1 due to 2 column format change and Process Measurement Accuracy (PMA) uncertainties. Transferred Surveillance Requirements 4.3.2 from page 3/4 3-15a due to repagination.
3/4 3-15a	4.3.2	Page deleted due to repagination of page 3/4 3-15.

LIST OF AFFECTED PAGES Continued

<u>PAGE</u>	<u>SECTION</u>	<u>CHANGE DESCRIPTION</u>
3/4 3-25	Table 3.3-4	Deleted TA, Z, & S columns from Table due to 2 column format change.
3/4 3-26	Table 3.3-4	Deleted TA, Z, & S columns from Table due to 2 column format change.
3/4 3-27	Table 3.3-4	Deleted TA, Z, & S columns from Table due to 2 column format change.
3/4 3-28	Table 3.3-4	Deleted TA, Z, & S columns from Table due to 2 column format change. Revised Allowable Value to Function 6.c., "Steam Generator Water Level - Low-Low," due to PMA uncertainties.
3/4 3-28a	Table 3.3-4	Deleted TA, Z, & S columns from Table due to 2 column format change.
3/4 3-28b	Table 3.3-4	Deleted TA, Z, & S columns from Table due to 2 column format change.
B 3/4 3-1	B 3/4.3.1, B 3/4.3.2	Deleted discussion on methodology of determining operability when setpoint is found to exceed the Allowable Value, due to 2 column format change.
B 3/4 3-1a	B 3/4.3.1, B 3/4.3.2	Deleted discussion on methodology of determining operability when setpoint is found to exceed the Allowable Value, due to 2 column format change. Included a paragraph from previous submittal (TSP 890022, Amendment 108) which was never incorporated. This change request supersedes the change referenced on letter number RC-93-0021, dated January 29, 1993.