

AUGUST 20 1982

DMB 014

DISTRIBUTION

Docket File

Docket No. 50-346

NRC PDR
L PDR
ORB#4 Rdg
DEisenhut
OELD
AEOD
IE-2
ACRS-10
TBarnhart-4
LSchneider
OGC
OPA
DBrinkman
RDiggs
ADe Agazio

RIngram
Gray File+4
ASLAB
EBlackwood
HOrnstein
RBosnak
OParr
WHazelton
LRubenstein
CRAB

Mr. Richard P. Crouse
Vice President, Nuclear
Toledo Edison Company
Edison Plaza
300 Madison Avenue
Toledo, Ohio 43652

Dear Mr. Crouse:

SUBJECT: ONCE-THROUGH STEAM GENERATOR REPAIR AND AUXILIARY FEEDWATER SYSTEM MODIFICATION - SAFETY EVALUATION REPORT

The NRC has completed its review and evaluation of your submittals dated July 15, 1982, July 30, 1982, August 6, 1982 and August 16, 1982. These submittals provide information relative to modifications Toledo Edison Company has made to the auxiliary feedwater system and repairs made to the once-through steam generators. These submittals also provide responses to our letter of June 23, 1982, pursuant to the provisions of 10 CFR 50.54(f).

We have concluded, based on our evaluation of your submittals in our enclosed Safety Evaluation Report that it is acceptable for Toledo Edison Company to resume power operation at the Davis-Besse Nuclear Power Station, Unit 1.

Sincerely,

APPROPRIATELY SIGNED BY

Gus C. Lainas, Assistant Director
for Operating Reactors
Division of Licensing

Enclosure:
Safety Evaluation
Report

cc w/enclosure:
See next page

8209230094 820820
PDR ADDCK 05000346
P PDR

OFFICE	ORB#4:DL	C-ORB#4:DL	C-MEB:DE	C:ASB:DSI	C-MEB:DE	AD:OR:DL	AD-CPS:DSI
SURNAME	ADe Agazio; cf JStolz	RBosnak	OParr	WHazelton	GLainas	LRubenstein	
DATE	8/19/82	8/19/82	8/19/82	8/19/82	8/19/82	8/19/82	8/17/82



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

August 20, 1982

Docket No. 50-346

Mr. Richard P. Crouse
Vice President, Nuclear
Toledo Edison Company
Edison Plaza
300 Madison Avenue
Toledo, Ohio 43652


Dear Mr. Crouse:

SUBJECT: ONCE-THROUGH STEAM GENERATOR REPAIR AND AUXILIARY FEEDWATER
SYSTEM MODIFICATION - SAFETY EVALUATION REPORT

The NRC has completed its review and evaluation of your submittals dated July 15, 1982, July 30, 1982, August 6, 1982 and August 16, 1982. These submittals provide information relative to modifications Toledo Edison Company has made to the auxiliary feedwater system and repairs made to the once-through steam generators. These submittals also provide responses to our letter of June 23, 1982, pursuant to the provisions of 10 CFR 50.54(f).

We have concluded, based on our evaluation of your submittals in our enclosed Safety Evaluation Report that it is acceptable for Toledo Edison Company to resume power operation at the Davis-Besse Nuclear Power Station, Unit 1.

Sincerely,


Gus C. Linares, Assistant Director
for Operating Reactors
Division of Licensing

Enclosure:
Safety Evaluation
Report

cc w/enclosure:
See next page

Toledo Edison Company

cc w/enclosure(s):

Mr. Donald H. Hauser, Esq.
The Cleveland Electric
Illuminating Company
P. O. Box 5000
Cleveland, Ohio 44101

Gerald Charnoff, Esq.
Shaw, Pittman, Potts
and Trowbridge
1800 M Street, N.W.
Washington, D. C. 20036

Paul M. Smart, Esq.
Fuller & Henry
300 Madison Avenue
P. O. Box 2088
Toledo, Ohio 43603

Mr. Robert B. Borsum
Babcock & Wilcox
Nuclear Power Generation Division
7910 Woodmont Avenue, Suite 208
Bethesda, Maryland 208

President, Board of County
Commissioners of Ottawa County
Port Clinton, Ohio 43452

Attorney General
Department of Attorney General
30 East Broad Street
Columbus, Ohio 43215

Harold Kahn, Staff Scientist
Power Siting Commission
361 East Broad Street
Columbus, Ohio 43216

Mr. James G. Keppler, Regional Administrator
U. S. Nuclear Regulatory Commission, Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Mr. Ted Myers
Manager, Nuclear Licensing
Toledo Edison Company
Edison Plaza
300 Madison Avenue
Toledo, Ohio 43652

U.S. Nuclear Regulatory Commission
Resident Inspector's Office
5503 N. State Route 2
Oak Harbor, Ohio 43449

Mrs. Julia Baldwin, Librarian
Government Documents Collection
William Carlson Library
University of Toledo
2801 W. Bancroft Avenue
Toledo, Ohio 43606

Regional Radiation Representative
EPA Region V
230 South Dearborn Street
Chicago, Illinois 60604

Ohio Department of Health
ATTN: Radiological Health
Program Director
P. O. Box 118
Columbus, Ohio 43216