

NOTICE OF VIOLATION

Grand Traverse Heart Institute
Traverse City, Michigan

License No. 21-26531-01
Docket No. 030-33324

During an NRC inspection conducted from March 2, 1994 through March 16, 1994, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C, the violation is listed below:

10 CFR 35.50(d) requires, in part, that a licensee repair or replace the dose calibrator if the accuracy error exceeds 10 percent.


Contrary to the above, on January 28, 1994, the licensee did not repair or replace the dose calibrator when the accuracy error exceeded 10 percent.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, Grand Traverse Heart Institute is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, Region III, 801 Warrenville Road, Lisle, Illinois, 60532-4351, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. If an adequate reply is not received within the time specified in this Notice, an order or a demand for information may be issued as to why the license should not be modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

MAR 28 1994

Dated _____



John D. Jones, Acting Chief
Nuclear Materials Inspection
Section 2