## U.S. NUCLEAR REGULATORY COMMISSION

## REGION III

Reports No. 50-266/82-19(DETP); 50-301/82-19(DETP)

Docket Nos. 50-266; 50-301

Licenses No. DPR-24; DPR-27

Licensee: Wisconsin Electric Power Company

231 W. Michigan Milwaukee, WI 53201

Facility Name: Point Beach Nuclear Plant, Units 1 and 2

Inspection At: Point Beach Site, Two Rivers, WI

Inspection Conducted: August 9-13, 1982

Date of Last Physical Security Inspection: June 22-26, 1981

Type of Inspection: Unannounced Physical Protection

Inspectors: All Forkey

for J. L. Belanger

Physical Protection Specialist

9/9/8 2 Date

Physical Protection Specialist

9/9/52

Approved By: Affactus, J. R. Creed, Chief,

9/9/82 Date

Inspection Summary

Inspection on August 9-13, 1982 (Reports No. 50-266/82-19(DETP);

50-301/82-19(DETP))

Areas Inspected: Included a review of Security Plan, Security Organization (Management/Personnel/Response); Security Program Audit; Records and Reports; Testing and Maintenance; Physical Barriers (Protected and Vital); Lighting; Assessment Aids; Access Control (Personnel/Packages/Vehicles); Detection Aids (Protected and Vital Areas); Alarm Stations; Communications; Independent Inspection; and Previous Items of Noncompliance. The inspection involved 72 inspector-hours onsite by two NRC inspectors. The inspection began during the backshift; twelve hours were accomplished during the offshift periods. The inspectors were accompanied by two auditors from the General Accounting Office.

> Enclosure Contains SAFEGUARDS INFORMATION Upon Separation This Page is Decontrolled

Enclosure Contains
SAFEGUARDS INFORMATION
Upon Separation This
Page is Decontrolled

Results: The licensee was found to be in compliance with NRC requirements within the areas examined during this inspection, except for the following five items:

- 1. Physical Barriers Protected Area: Failure to adequately maintain the protected area physical barrier. (Paragraph 13)
- 2. Physical Barriers Protected Area: Failure to adequately maintain the isolation zone. (Paragraph 13)
- 3. Physical Barriers Protected Area: A portal into the protected area contained the incorrect type of locking mechanism as specified in the security plan. (Paragraph 13)
- 4. Alarm Stations: Failure to properly maintain an item of equipment within the Central Alarm Station (Paragraph 22)
- 5. Detection Aids Protected Area: The protected area intrusion alarm system did not detect all test penetrations conducted by the inspector. (Paragraph 20)

(DETAILS - UNCLASSIFIED SAFEGUARDS INFORMATION)