## MAR 4 1987

Advanced Medical Systems, Inc. Seymore S. Stein President 1020 London Road Cleveland, OH 44110

License No. 34-19089-01

Gentlemen:

This refers to the special inspection conducted on December 4, 1986 through February 18, 1987, of activities authorized by NRC Byproduct Material License No. 34-19089-01, and to the discussion of our findings with Mr. Howard Irwin, RSO, at the conclusion of the inspection.

This special inspection was initiated as a result of our receipt of an allegation pertaining to releases of radioactive material to the Sanitary Sewage System. A copy of Inspection Report No. 030-16055/87-001(DRSS), which details the allegation and NRC findings, is enclosed.

No violations of NRC requirements or specific license conditions were identified during this special inspection.

Sincerely

Darrel G. Wiedeman, Chief Nuclear Materials Safety

Section 1

Enclosure: Inspection Report No. 030-16055/87-001(DRSS)

cc w/enclosure: DCS/RSB (RIDS)

8703110221 REG3 LIC30 34-19098-01 PDR

Burgin/nma

McCann

RIII BIN Mallett

IE07