



231 W Michigan PO Box 2046, Milwaukee, WI 53201-2046

VPNPD-94-034 NRC-94-027

March 30, 1994

Document Control Desk
U. S. NUCLEAR REGULATORY COMMISSION
Mail Station P1-137
Washington, DC 20555

Gentlemen:

DOCKET 50-266
STEAM GENERATOR INSPECTION PLAN
POINT BEACH NUCLEAR PLANT, UNIT 1

This letter is to inform you that we will not be performing steam generator eddy current examinations during the spring 1994 Unit 1 refueling outage. Point Beach Nuclear Plant (PBNP) Technical Specification 15.4.2.A.4(c) allows a steam generator inservice inspection frequency extension to 40-month intervals if two consecutive inservice inspections covering a time span of at least 12 months identify less than 5% of the total number of tubes examined degraded and none defective (C-1 category). Because the results of the 1992 and 1993 Unit 1 steam generator inspections are Category C-1, we will not perform eddy current examinations during the upcoming Unit 1 refueling outage. This will allow a significant cost savings for Wisconsin Electric Power Company and an associated reduction in personnel exposure.

If you require any further information, please contact Mr. Kevin Crowley at (414) 755-6284.

Sincerely,

Bob Link

Vice President Nuclear Power

cc: NRC Resident Inspector

NRC Regional Administrator

A001 1/c