

H. B. ROBINSON STEAM ELECTRIC PLANT Post Office Box 790 Hartsville, South Carolina 29550

September 15, 1982

Robinson File No: 13510C

Serial: RSEP/82-11493

USNRO REGION TLANTA, GEORG

Mr. James P. O'Reilly Regional Administrator U. S. Nuclear Regulatory Commission Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261
LICENSE NO. DPR-23
LICENSEE EVENT REPORT 82-011

Dear Mr. O'Reilly:

In accordance with Section 6.9.2 of the Technical Specifications for the H. B. Robinson Steam Electric Plant, Unit 2, the enclosed Licensee Event Report is submitted. This report fulfills the requirements for a written report within thirty (30) days of a reportable occurrence and is in accordance with the format set forth in NUREG-0161, July, 1977.

This report is late due to an administrative oversight. Changes have been implemented within our Regulatory Compliance Subunit which should prevent this type of error from occurring in the future.

Very truly yours,

R. B. Starkey, Jr. General Manager

H. B. Robinson SEG Plant

HTC/bss

Enclosure

cc: R. C. DeYoung (30)
R. A. Hartfield (3)

GFFICIAL COPYLA