



University of Lowell

One University Avenue

Lowell, Massachusetts 01854

(617) 452-5000

September 7, 1982

Docket No. 50-223

License No. R-125

Mr. Richard W. Starostecki
Division of Project and Resident Programs
U.S. Nuclear Regulatory Commissions
Region I
King of Prussia, PA 19406

Dear Sir:

In response to your Notice of violation dated August 11, 1982, the University of Lowell submits the following information. Following your inspection of June 16, 1982, procedures were prepared, reviewed and approved as required by Technical Specifications. These procedures covered all of the areas identified as being inadequate in your inspection report. These procedures were reviewed by your office via telephone on June 17, 1982. All subsequent activities dealing with the Co-60 source have been conducted according to these procedures.

All personnel responsible for the issuing and implementation of procedures were reminded that Technical Specifications and 10CFR require that written, approved procedures are required for these kinds of activities.

We consider the University of Lowell to be in full compliance as of June 17, 1982.

Sincerely yours,

Thomas J. Wallace
Nuclear Reactor Supervisor

cc Dr. G.H. Kegel
Dr. L. Beghian