

MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

JAMES P. McGAUGHY, JR. ASSISTANT VICE PRESIDENT

September 22, 1982

Office of Inspection & Enforcement U.S. Nuclear Regulatory Commission Region II 101 Marietta St., N.W., Suite 3100 Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

EP 24 A

ANTA. GEORG

SUBJECT: Grand Gulf Nuclear Station

Unit 1

Docket No. 50-416 License No. NPF-13 File 0260/L-835.0

Fire Detection Instrumentation

Inoperability

Reference: LER 82-054/03 L-0

AECM-82/419

On August 24, 1982, the fire detection instrumentation for the fuel handling and ventilation equipment area went into alarm and would not clear. A Limiting Condition for Operation was entered pursuant to T.S.3.3.7.9. Investigation showed no smoke or fire. Attached is LER 82-054/03 L-0.

Yours truly, John D Ruhardon John J. P. Mc baughy, JR.

JPM:lm Attachment

cc: Mr. N. L. Stampley (w/a)

Mr. R. B. McGehee (w/o)

Mr. T. B. Conner (w/o)

Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a) Office of Inspection & Enforcement U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Document Control Desk (w/a) U.S. Nuclear Regulatory Commission Washington, D.C. 20555

TE 22