



Department of Energy
Albuquerque Operations Office
P.O. Box 5400
Albuquerque, New Mexico 87115

SEP 26 1990

Mr. Paul H. Lohaus
Branch Chief, Operations Branch
Division of Low-Level Waste
Management & Decommissioning
Office of Nuclear Materials Safety
and Safeguards
Mail Stop 5-E-4
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Dear Mr. Lohaus:

Enclosed is a copy of the Albuquerque Operations Manual, Section 9.2.10, which provides guidance for performing close-out inspections of construction activities at Uranium Mill Tailing Remedial Action sites. The document is provided in response to your letter dated August 23, 1990. Our proposal for conducting close-out inspections, submitted to R. Hall in a letter dated June 6, 1990, is now superseded by the enclosed manual.

Should you have any questions, please contact Milt Scoutaris of my staff at FTS 8-5-5630.

Sincerely,

Mark L. Matthews
Project Manager
Uranium Mill Tailings Remedial Action
Project Office

Enclosure

cc w/enclosure:
F. Bosiljevac, UMTRA
C. Smythe, UMTRA
M. Scoutaris, UMTRA
M. Abrams, UMTRA
B. Bearden, JEG

9010020047 900926
PDR WASTE
WM-39 PDC

WM-39
NHO-4/11