TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401 1750 Chestnut Street Tower II

September 24, 1982

Mr. James P. O'Reilly, Director U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE V. LLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET NO. 50-327 - FACILITY OPERATING LICENSE DPR-77 - REPORTABLE OCCURRENCE REPORT SQRO-50-327/82107

The enclosed report provides details concerning the shield building annulus door being left open causing the emergency gas treatment system to be declared inoperable. This report is submitted in accordance with Sequoyah unit 1 Technical Specification 6.9.1.12.b.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

Director of Nuclear Power

Enclosure cc (Enclosure):

> Document Control Desk U.S. Nuclear Regulatory Commission Washington, DC 20555

Records Center Institute of Nuclear Power Operations Suite 1500 1100 Circle 75 Parkway Atlanta, Georgia 30339

NRC Inspector, Sequoyah

TE 22

8210010108 820924 PDR ADOCK 05000327