The Goodyear Tire and Rubber Company ATTN: Patrick J. Reilly Radiation Safety Officer 142 Goodyear Boulevard Akron, OH 44316

Gentlemen:

This refers to the routine safety inspection conducted by Mr. W. J. Slawinski of this office on September 15, 1982, of activities authorized by NRC Byproduct Material Licenses No. 34-00508-04 and No. 34-00508-06 and to the discussion of our findings with you at the conclusion of the inspection and to the telephone conversations with you and Mr. Ray DiRossi on September 21, 1982.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

In addition to the above areas, the inspector examined actions described in your letter dated November 6, 1979, regarding the leak testing and disposal of a carbon-14 sealed source which was possessed under License No. 34-00508-03. Also examined were your corrective actions regarding the apparent item of noncompliance found during our June 8, 1979 inspection of License No. 34-00508-04. We have no further questions regarding these matters.

No items of noncompliance with NRC requirements were identified during the course of this inspection of License No. 34-00508-06.

However, during the inspection of License No. 34-00508-04, certain of your activities appeared to be in noncompliance with NRC requirements, as specified in the enclosed Appendix. A written response is required.

8210050001 820930 NMS LIC30 34-00508-04 PDR SEP 3 0 1982

License No. 34-00508-04 30 - 7038 License No. 34-00508-06 30 - 5628

DMB IE 07

The Goodyear Tire and Rubber Company

1

The responses directed by this letter (and the accompanying Notice) are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely, uslema

D. J. Sreniawski, Chief Materials Radiation Protection Section 2

Enclosure: Appendix, Notice of Violation

cc w/encl: DMB/Document Control Desk (RIDS)

RIII SKL Slawinski/np 9/28/82

RIII Sreniaw

2