Docket No. 50-373

Commonwealth Edison Company ATTN: Mr. Cordell Reed Vice President Post Office Box 767 Chicago, IL 60690

Gentlemen:

Thank you for your letter dated September 23, 1982, informing us of the steps you have taken to correct the noncompliance identified in our letter dated August 24, 1982. It is our understanding, as a result of a telephone conversation on September 27, 1982 between Mr. T. Borsym of your staff and Mr. J. Belanger of this office, that the corrective action taken to avoid further noncompliance detailed in your response to item No. 4 contained an error in that the test frequency stated should read twice per shift rather than twice a day. It your understanding of this test commitment is different from that stated above, please advise this office within twenty days of the date of this letter. We will examine your corrective actions taken during future inspections.

We also wish to bring your attention to the protective marking requirements for Unclassified Safeguards Information. As discussed with Mr. Borzym of your staff, the protective markings of your response were confusing and included contradictory stamps. This did not represent noncompliance with requirements but could lead to confusion on the part of those handling the documents.

Your cooperation with us is appreciated.

Sincerely,

Original Signed by J. R. Miller

James R. Miller, Chief Technical Inspection Branch

Distribution: See attached list

 cc: L. O. DelGeorge, Director of Nuclear Licensing G. J. Diederich, Station Superintendent

cc w/ltr dtd 9/23/82 w/UNCLASSIFIED SAFEGUARDS INFORMATION: IE Files MMSS/SGPL NRR/DL/SSPG

cc w/ltr dtd 9/23/82 w/o UNCLASSIFIED SAFEGUARDS INFORMATION: D. L. Shamblin, Site Construction Superintendent T. E. Quaka, Quality Assurance Superintendent R. H. Holyoak, Project Manager DMB/Document Branch Resident Inspector, RIII Karen Borgstadt, Office of Assistant Attorney General