

SEP 29 1982

Bureau of Engineering  
City of Akron, Ohio  
ATTN: Mr. Thomas Butler  
Radiation Protection Officer  
1420 Triplett Boulevard  
Akron, Ohio 44306

License No. 34-20183-01

30 - 18063

Gentlemen:

This refers to the routine safety inspection conducted by Mr. W. J. Slawinski of this office on September 16, 1982, of activities authorized by NRC Byproduct Material License No. 34-20183-01 and to the discussion of our findings with Mr. Jerome Gergosky at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as specified in the enclosed Appendix. A written response is required.

The responses directed by this letter (and the accompanying Notice) are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

*D. J. Sreniawski*  
D. J. Sreniawski, Chief  
Materials Radiation Protection  
Section 2

Enclosure: Appendix,  
Notice of Violation

cc w/encl:  
DMB/Document Control Desk (RIDS)

RIII  
*DJB for*  
Slawinski/sv  
9/27/82

RIII  
*DJB*  
Sreniawski  
9/29/82

8210050129 820929  
NMS LIC30  
34-20183-01 PDR

IE HQ File Copy  
DMB IE-07