




GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

September 27, 1982
RBG- 13,440
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011




Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-71

On August 27, 1982, Gulf States Utilities Company (GSU) notified the Region IV Office of a condition potentially reportable under 10CFR50.55(e) concerning inconsistencies found in the QA program at the W. J. Woolley Company, the manufacturer of personnel air locks at River Bend Station (DR-71).

GSU's investigation is not yet complete. An Interim or Final Status Report will be provided by January 15, 1983.

Sincerely,


for J. E. Booker
Manager-Engineering & Licensing
River Bend Nuclear Group

JEB/LAE/kt

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

R. L. Brown (RRI)

IE27

8210050201 820927
PDR ADOCK 05000458
S PDR