

September 22, 1982

D.J. Sreniawski, Chief Materials Radiation Protection, Section 2 U.S. Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137

Re: License No. 21-04127-06 License No. 21-04127-08

Dear Madam or Sir:

This is in response to your notice of violation dated September 8, 1982 regarding the timer accuracy determinations required as part of monthly spot measurements on our two teletherapy licenses. You stated and we agreed that the timer accuracy was not made for the months of June, May, and March of 1982 and several months in 1981. We wish to assure you that, for both teletherapy units: (1) the corrective action has been taken starting with the month of September, 1982 by making timer accuracy determination, (2) we are enforcing the monthly spot checks to include timer accuracy by devising a form that clearly shows the timer accuracy determination as a part of the spot checks; and (3) the full compliance has already been achieved as of September 1982.

We hope this satisfies the response requirement within thirty days of your notice.

Sincerely yours,

George P. Caralis

Associate Administrator

GPC/ljp

cc: John J. Kim, Ph.D., Chief Radiation Safety Officer William Powers, M.D., Radiation Oncology Center Kenneth Whipple, Administration