PRELIMINARY NOTIFICATION OF EVENT OR UNUSUAL OCCURRENCE PNO-II-90-64

This preliminary notification constitutes EARLY notice of events of POSSIBLE safety or public interest significance. The information is as initially received without verification or evaluation, and is basically all that is known by the Region II staff on this date.

BAD BALL	Duke Power Company McGuire Unit 1 Docket No. 50-369	Licensee Emergency Classification: Notification of Unusual EventAlertSite Area Emergency
		General Emergency X Not Applicable

SUBJECT: SHUTDOWN EXCEEDING 48 HOURS

At approximately 5:20 p.m., (EDT) on October 15, 1990, Unit 1 commenced a shutdown from 95 percent power due to high vibration observed on "C" low pressure turbine. Subsequently, Unit 1 entered Mode 5 at 11:50 p.m., on October 16, 1990. At the present time, the licensee believes that the intercept valve on the "C" low pressure turbine may have caused the high vibration. The licensee is investigating the problem and evaluating possible damage to the "C" low pressure turbine. Estimated time to restart is approximately 10 days. Unit 2 is at Mode 5.

The licensee has not issued a press release. State and local authorities were not notified.

The NRC resident inspector was notified.

This information is current as of 11:30 a.m., on October 17, 1990.

CONTACT: S. Ninh - 841-2797

DISTRIBUTION:

One White Flint North Chairman Carr	M'land Nat'l Bank Bldg IRM	Regions MAIL TO:	DCS (Original IE 34) DOT (Transportation Only)
Comm. Rogers Comm. Curtiss Comm. Remick OGC OCA	OIG AEOD NRC Ops Ctr	Region II Region III FAX TO: Region IV Region V	INPO /2:35 LICENSEE (Corporate)/237 RII Resident /238
GPA/SLITP/PA EDO NRR	Nicholson Lane RES	Phillips Bldg ACRS	
NMSS OE	L Street PDR	EWW ASLAP	

5520: 10/17/90 @ 11:50 am TO REGIONS AND HQ

9010300271 901017 PDR I&E PNO-11-90-064 PNU 1034