

RICHARD P. CROUSE Vice President Nuclear (419) 259-5221

Docket No. 50-346 License No. NPF-3 Serial No. 863 September 29, 1982

Director of Nuclear Reactor Regulation Attention: Mr. John F. Stolz Operating Reactor Branch No. 4 Division of Operating Reactors United States Nuclear Regulatory Commission Washington, D.C. 20555

Dear Mr. Stolz:

This is in response to your letter dated July 21, 1982 (Log No. 1036) concerning a schedule for responding to the attached information for NUREG-0737 Item II.B.3; (Post Accident Samplir System) Request for Information. Toledo Edison expects to provid_ , response by the end of March 1983 for Davis-Besse Nuclear Power Station Unit No. 1.

Very truly yours,

Kolom

RPC:GAB:lab

10050333 8209 PDR ADUCK 050003

cc: DB-1 NRC Resident Inspector

A046

THE TOLEDO EDISON COMPANY EDISON PLAZA 300 MADISON AVENUE TOLEDO, OHIO 43652