U.S. NUCLEAR REGULATORY COMMISSION

## REGION III

Report No. 99990080/82-05(DETP)

Ducket No. 99990080

License No. XSNM-1627

Licensee: Transnuclear, Incorporated

One North Broadway White Plains, NY 10601

Inspection At: Last Terminal in the United States

Inspection Conducted: September 14, 1982

Type of Inspection: Routine Safeguards Inspection of Nuclear Material

Inspector:

J.R. Cued

T. J. Madeda Physical Protection Specialist

Approved By:

J. R. Creed, Chief Safeguards Section 9/27/82

Inspection Summary

Inspection on September 14, 1982 (Report No. 99990080/82-05(DETP))

Areas Inspected: Included a review of General Performance Objectives;
In-Transit Performance, General Physical Protection System Requirements;
Security Organization and Audit; Response and Contingency Plan/Procedures;
Access Control; Road Shipment Requirements; and Delivery and Receiving
Requirements. The inspection involved three inspector-hours onsite by one
NRC inspector. The inspection began during the dayshift period.
Results: The licensee was found to be in compliance with NRC requirements within the areas examined during the inspection.

(Details - UNCLASSIFIED SAFEGUARDS INFORMATION)

Enclosure Contains
SAFEGUARDS INFORMATION
Upon Separation This
Page is Decontrolled