



CONNECTICUT YANKEE ATOMIC POWER COMPANY

MERLIN, CONNECTICUT

P. O. BOX 270 HARTFORD, CONNECTICUT 06101

TELEPHONE
203-666-6911

September 24, 1982

Docket No. 50-213
A02623

Director of Nuclear Reactor Regulation
Attn: Mr. Dennis M. Crutchfield, Chief
Operating Reactors Branch #5
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

References: (1) D. M. Crutchfield letter to W. G. Council, dated
June 28, 1982.

Gentlemen:

Haddam Neck Plant
SEP Topic III-3.C, Inservice Inspection of Water Control Structures

Reference (1) forwarded the Staff's evaluation of SEP Topic III-3.C, Inservice Inspection of Water Control Structures, for the Haddam Neck Plant. Connecticut Yankee Atomic Power Company (CYAPCO) has reviewed Reference (1) and has no comments.

The need to implement an inservice inspection program for water control structures will be evaluated during the Integrated Assessment.

Very truly yours,

CONNECTICUT YANKEE ATOMIC POWER COMPANY

W. G. Council
Senior Vice President

A035