

APPENDIX A

NOTICE OF VIOLATION

Professional Service Industries, Inc.
Pittsburgh Testing Laboratories, Division
Pittsburgh, Pennsylvania 15220

Docket No. 030-05985
License No. 37-00276-25

As a result of the inspection conducted on September 13, 25 and 26, 1990, and in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (Enforcement Policy) (1990), the following violations were identified:

- A. 10 CFR 34.11(d)(1) requires, in part, that a licensee's inspection program include observation of the performance of each radiographer during an actual radiographic operation at intervals not to exceed three months.

Contrary to the above, on September 10 and 11, 1990, a PSI Radiographer performed radiography without having been observed during an actual radiographic operation during the previous three months.

This is a Severity Level IV violation. (Supplement VI)

Pursuant to the provisions of 10 CFR 2.201, Professional Service Industries, Inc., Pittsburgh Testing Laboratories Division, is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

OFFICIAL RECORD COPY

ML DL PRO - 0003.0.0
11/01/90

9011140184 901106
REG1 LIC30
37-00276-25 PDC