

October 1, 1982
PNS-LI-82-415, ARRO REG

Mr. James P. O'Reilly Regional Administrator, Region II U.S. Nuclear Regulatory Commission 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 251-82-13

TURKEY POINT UNIT 4

DATE OF OCCURRENCE: SEPTEMBER 6, 1982

TECHNICAL SPECIFICATION 3.1.6.b

RCS PRESSURE TRANSIENTS

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30 day notification of the subject occurrence.

Very truly yours,

J.W. Williams, Jr. Vice President

Nuclear Energy

PLP/mbd

Attachment

cc: Director, Office of Inspection and Enforcement (30)

Harold F. Reis, Esquire

File 933.1 TP

OFFICIAL COPY: