



November 19, 1990

Docket No. 030-03754
Byproduct License No. 06-00217-06

Mr. Thomas T. Martin
Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, Pennsylvania 19406

Dear Mr. Martin:

I would like to express my appreciation for the time you and your staff took to visit our facilities in Windsor. Most of the issues we discussed centered on the performance of the Fuel Manufacturing Facility; you did make one observation to me on our Byproduct License operations, however, which I subsequently pursued with my staff. I am referring to your comment on the cleanliness of our Outage Services Facilities.

Following our discussion, I met that same evening with the Vice President of Nuclear Services, Bill Skibitsky. We agreed with your assessment that no radiological or safety concern exists. Although our Outage Services Facility has an excellent record for radiological controls and maintains the strong anti-hot particle program you observed during your visit, we nevertheless decided to perform a special review of our current practices and housekeeping rules.

Once again, we appreciate your time and effort to visit the Windsor Facilities and welcome your return at any time. If I can be of any assistance on these matters, please don't hesitate to contact me.

Very truly yours,

Shelby T. Brewer

9012040238 901119
REG1 LIC30
06-00217-06 PNU

STB:kll

ABB Combustion Engineering Nuclear Power

Shelby T. Brewer
President

Combustion Engineering Inc.
1000 Prospect Hill Road
Post Office Box 500
Windsor, Connecticut 06095-0500

Telephone (203) 285-5805
Fax (203) 285-4923