PRELIMINARY NOTIFICATION OF EVENT OR UNUSUAL OCCURRENCE PNO-III-90-78 Date November 26, 1990

This preliminary notification constitutes EARLY notice of events of POSSIBLE safety or public interest significance. The information is as initially received without verification or evaluation, and is basically all that is known by the Region III with staff on this date.

Facility: Syncor Corp.

Akron, Ohio

34-19008-01 (MD)

Licensee Emergency Classification General Emergency Site
Alert Unusual Event Site Area Emergency

Subject: MISLABELING OF D'AGNOSTIC RADIOPHARMACEUTICALS

On November 23, 1990, 12 individual doses of a radiopharmaceutical containing technetium-99m were mislabeled resulting in 11 diagnostic misadministrations. The individual dose labels indicated the material was Tc99m-MDP, a bone imaging agent. In fact, the material was Tc-99m-DTPA, a kidney imaging radiopharmaceutical. The doses were distributed to 8 Akron area hospitals and 11 of them were used for diagnostic tests on patients. The error was discovered when the hospitals reported that the test results were different than those anticipated.

The licensee attributed the error to a misreading of the label on the vial containing the bulk quantity of the material.

Region III (Chicago) will review the circumstances of the error, determine causal factors, and evaluate corrective actions during a special inspection of the licensee.

The State of Ohio will be notified. The information in this Preliminary Notification has been reviewed with licensee management.

Region III was notified of this incident by the licensee at 2:30 p.m. on November 23, 1990. This information is current as of 10 a.m., November 26, 1990.

CONTACT:

WKS W. Schultz

388-5526

388-5612

DISTRIBUTION:

HEADQUARTERS	OFFICES
Chairman Carr	NMSS
Comm. Rogers	GPA:SP
Comm. Curtiss	GPA:PA
Comm. Remick	GPA:CA
EDO	*01G
Gen. Counsel	*ASLAP
NRR	Research
AEOD	IRM
Enforcement	ACRS

REGIONS	MAIL TO:
Region I	DCS (Orig)
Region II	DOT (Trans.
Region IV	Only)
Region V	

FAX TO: INPO NSAC NRC OPS CTR 1:48 PDR (8/634-3343) 1:50

\*Denotes a Displaywriter/PC not an IBM 5520 Terminal.

Rev. 10/23/90

9012050019 901126 PDR 18E PNO-111-90-078 PDC